

**United States Environmental Protection Agency
Region 5
77 West Jackson Boulevard
Chicago, Illinois 60604**

US EPA RECORDS CENTER REGION 5



549066

Date: December 19, 2017
Site Visit: Site Visit, Rasmussen's Dump, Brighton, Michigan
From: Howard Caine, RPM *ihmc*
To: File

Introduction and Purpose

The United States Environmental Protection Agency (U.S. EPA) Region 5 and Michigan Department of Environmental Quality (MDEQ) conducted a Site Visit at the Rasmussen's Dump site on December 1, 2017.

Participants

Howard Caine, U.S. EPA

Keith Krawczyk, MDEQ

Jeff "Bart" Bartholomy, GHD

Steve Rapai, GHD

Inspection

The site was toured. Groundwater monitoring wells and gas vents were observed. The groundwater monitoring wells were locked. The perimeter of the landfill on the west and south ends were observed in addition to the top of the landfill. No holes were observed in the top of the landfill. A tour of the equipment building was completed. The fence looked to be in good shape. One section could use some maintenance, but GHD staff said that there has never been an issue with trespassers.



Photo 1: Compressor for Sparge System



Photo 2: Ozone Generator



Photo 3: Controller for Ozone Generator



Photo 4: Buckled Fencing on the South End of the Landfill



Photo 5: South End of the Rasmussen's Dump



Photo 6: Rip Rap and Drainage for Landfill Runoff



Photo 7: Groundwater Monitoring Well



Photo 8: North End of Rasmussen's Dump



Photo 9: Gas Vent



Photo 10: Top of Dump facing Rasmussen Salvage



Photo 11: North Side of Rasmussen's Dump




Photo 12: Equipment Building



Photo 13: Groundwater Monitoring Well North of Spicer Road



Photo 14: Groundwater Monitoring Well South of Spicer Road